## **ROW SHUT OFF CARRIAGE UNIT**

MODEL; 218-F8R BLACK GROUND WIRE FROM ALL SELENOIDS GOES TO GROUNDING BOLT A PT. S94309 SINGLE JUMPER PT. S94509 DOUBLE JUMPER SLECTRO SOLENOID COVER PT. S94007 Replacement PT. S99201 SLECTRO WHEEL COVER

PT. S94004 THE POSITIVE BROWN, BLACK, RED AND GREEN WIRES GO TO THE CABLE CONNECTION LEADING TO THE TRACTOR MOUNTED CONTROL BOX. SOLENOID. QUANTITY REQUIRED DEPENDS ON THE SIZE OF THE UNIT. PT. D610-A1V12 F09514 Replacement PT. D610-B1V12 SLECTRO SOLENOID CARRIAGE SAME MOUNT ANGLE SHOWN IN DRAWING BELOW FROM BOTTOM VIEW PT. S94702 1/4" x 3" ROD WELDED TO CARRIAGE Ð SLECTRO BACK MOUNT BRACKET COIL SPRING (CONE) PT. 770-2110 (part # S94203)-1/4 " - 20 X 3 /4" THESE HOLES ARE USED AS A MOUNT TO THE EXISTING PLANTER UNIT LOOSEN BOLTS, INSERT BRACKET AND TITGHTEN. LOCK NUT PT. T10581 1/4" - 20 X 1 CARRIAGE SCREW WHEEL LEVER FORK PT. S94302 SLECTRO GANG PIVOT PIN GROUNDING BOLT PT. S94011 -SPACER CONNECTION BOLT TYPICAL FOUR (4) PLACES SLECTRO FRONT MOUNT BRACKET WHEEL CARRIER HUB (0) HOLES MUST BE DILLED IN THE PLANTER SEED RELEASE WHEEL CARRIAGE ACCORDING TO THE FOLLOWING DRAWING ✓ Pin typ. two (2) places TO ACCEPT THE FRONT MOUNT BRACKET -- WHEEL · 3/8" - 16 X 1 HEX CAP SCREWS WHEEL CARRIER AXLE PT. S94207 WHEEL CARRIER TUBE S94107 ~ 13/32" DIA. MOUNTING BRACKET TYPICAL FOUR (4) PLACES

SLECTRO COMPANY AVON, SOUTH DAKOTA

(605) 286-3221